




UT Date 03/05/2025 Observers KS

File	Title	Filt	Exp	UT	RA	Dec	HA	Air	Prop	Bin	Comments
comp.7098	parked	RV31	270	22:55	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	Test comp; too short; mirror covered; RV31 2x3
comp.7099	parked	RV31	1200	23:02	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
comp.7100	parked	Ca19	1200	23:27	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
domeflat.7101	parked	Ca19	90	23:50	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
domeflat.7102	ring250	Ca19	90	00:23	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
comp.7103	ring250	OB25	600	00:28	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x2	
comp.7104	ring250	OB25	180	01:03	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
comp.7105	ring250	RV31	150	01:19	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
ring250.7106	ring250	RV31	0	01:25	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	Bias; 2x3
ring250.7107	ring250	RV31	0	01:25	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
ring250.7108	ring250	RV31	0	01:26	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
ring250.7109	ring250	RV31	0	01:26	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
ring250.7110	ring250	RV31	0	01:26	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
ring250.7111	ring250	RV31	0	01:26	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
ring250.7112	ring250	RV31	0	01:27	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
ring250.7113	ring250	RV31	0	01:27	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
ring250.7114	ring250	RV31	0	01:27	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
ring250.7115	ring250	RV31	0	01:28	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x3	
ring250.7116	ring250	RV31	0	01:29	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x2	Bias; 2x2
ring250.7117	ring250	RV31	0	01:29	-01:00:00.0	-100:00:00	-00:00	1.00	calibration	2x2	


UT Date 03/05/2025 Observers KS

File	Title	Filt	Exp	UT	RA	Dec	HA	Air	Prop	Bin	Comments
ring250.7118	ring250	RV31	0	01:30	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
ring250.7119	ring250	RV31	0	01:30	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
ring250.7120	ring250	RV31	0	01:30	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
ring250.7121	ring250	RV31	0	01:31	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
ring250.7122	ring250	RV31	0	01:31	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
ring250.7123	ring250	RV31	0	01:32	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
ring250.7124	ring250	RV31	0	01:32	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
ring250.7125	ring250	RV31	0	01:32	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
comp.7126	ring250	RV31	150	01:34	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	RV31 2x3
comp.7127	ring250	RV31	150	01:36	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
comp.7128	ring250	RV31	150	01:39	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
domeflat.7129	ring250	RV31	8	01:42	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
domeflat.7130	ring250	RV31	8	01:43	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
domeflat.7131	ring250	RV31	8	01:44	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
domeflat.7132	ring250	RV31	8	01:44	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
domeflat.7133	ring250	RV31	8	01:45	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
domeflat.7134	ring250	RV31	8	01:45	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
domeflat.7135	ring250	RV31	8	01:46	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
comp.7136	ring250	OB24	180	01:49	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	OB24 2x2
comp.7137	ring250	OB24	180	01:52	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	




UT Date 03/05/2025 Observers KS

File	Title	Filt	Exp	UT	RA	Dec	HA	Air	Prop	Bin	Comments
comp.7138	ring250	OB24	180	01:56	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
domeflat.7139	ring250	OB24	5	02:00	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
domeflat.7140	ring250	OB24	5	02:00	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
domeflat.7141	ring250	OB24	5	02:01	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
domeflat.7142	ring250	OB24	5	02:02	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
domeflat.7143	ring250	OB24	5	02:02	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
domeflat.7144	ring250	OB24	5	02:03	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
domeflat.7145	ring250	OB24	5	02:04	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
domeflat.7146	n2506mmt_bins3	OB24	5	02:32	+08:00:03.7	-10:46:35	-01:59	1.59	2025A-UAO- G153	2x2	
comp.7147	n2506mmt_bins3	OB24	180	02:33	+08:00:03.7	-10:46:35	-01:58	1.59	2025A-UAO- G153	2x2	
n2506mmt_bins3_1.7148	n2506mmt_bins3	OB24	1800	02:38	+08:00:03.6	-10:46:30	-01:54	1.57	2025A-UAO- G153	2x2	Thin clouds; WFS=1.65"
n2506mmt_bins3_1.7149	n2506mmt_bins3	OB24	1800	03:08	+08:00:03.6	-10:46:30	-01:23	1.46	2025A-UAO- G153	2x2	
n2506mmt_bins3_1.7150	n2506mmt_bins3	OB24	1800	03:39	+08:00:03.6	-10:46:30	-00:53	1.39	2025A-UAO- G153	2x2	
n2506mmt_bins3_1.7151	n2506mmt_bins3	OB24	1800	04:09	+08:00:03.6	-10:46:30	-00:22	1.36	2025A-UAO- G153	2x2	
n2506mmt_bins3_1.7152	n2506mmt_bins3	OB24	1800	04:40	+08:00:03.6	-10:46:30	+00:07	1.35	2025A-UAO- G153	2x2	
n2506mmt_bins3_1.7153	n2506mmt_bins3	OB24	1800	05:10	+08:00:03.6	-10:46:30	+00:38	1.37	2025A-UAO- G153	2x2	
n2506mmt_bins3_1.7154	n2506mmt_bins3	OB24	1800	05:40	+08:00:03.6	-10:46:30	+01:08	1.43	2025A-UAO- G153	2x2	Clear
n2506mmt_bins3_1.7155	n2506mmt_bins3	OB24	1800	06:11	+08:00:03.6	-10:46:30	+01:39	1.51	2025A-UAO- G153	2x2	
comp.7156	n2506mmt_bins3	OB24	180	06:42	+08:00:03.7	-10:46:35	+02:10	1.65	2025A-UAO- G153	2x2	
tz001494_gf1_1.7157	tz001494_gf1	RV31	600	07:05	+12:21:48.0	-14:00:48	-01:48	1.64	2025A-SAO- 24	2x3	Clear; WFS=2.29", though FWHM plots look better than that



UT Date 03/05/2025 Observers KS

File	Title	Filt	Exp	UT	RA	Dec	HA	Air	Prop	Bin	Comments
tz001494_gf1_1.7158	tz001494_gf1	RV31	600	07:15	+12:21:48.0	-14:00:48	-01:38	1.60	2025A-SAO-24	2x3	Seeing worsened during this exp
tz001494_gf1_1.7159	tz001494_gf1	RV31	600	07:25	+12:21:48.0	-14:00:48	-01:27	1.56	2025A-SAO-24	2x3	
tz001494_gf1_1.7160	tz001494_gf1	RV31	600	07:36	+12:21:48.0	-14:00:48	-01:17	1.53	2025A-SAO-24	2x3	Extra exps for poor seeing
tz001494_gf1_1.7161	tz001494_gf1	RV31	600	07:46	+12:21:48.0	-14:00:48	-01:06	1.51	2025A-SAO-24	2x3	
domeflat.7162	tz001494_gf1	RV31	8	07:57	+12:21:48.1	-14:00:52	-00:56	1.48	2025A-SAO-24	2x3	
comp.7163	tz001494_gf1	RV31	150	07:58	+12:21:48.1	-14:00:52	-00:55	1.48	2025A-SAO-24	2x3	
domeflat.7164	umin_2025	RV31	8	08:17	+15:09:46.2	+67:15:24	-03:22	1.44	2025A-SAO-10	2x3	
comp.7165	umin_2025	RV31	150	08:18	+15:09:46.2	+67:15:24	-03:21	1.44	2025A-SAO-10	2x3	
umin_2025_1.7166	umin_2025	RV31	2700	08:21	+15:09:46.3	+67:15:19	-03:18	1.43	2025A-SAO-10	2x3	Clear; WFS=1.37"
umin_2025_1.7167	umin_2025	RV31	2700	09:07	+15:09:46.3	+67:15:19	-02:33	1.34	2025A-SAO-10	2x3	
umin_2025_1.7168	umin_2025	RV31	2700	09:52	+15:09:46.3	+67:15:19	-01:47	1.28	2025A-SAO-10	2x3	
comp.7169	umin_2025	RV31	150	10:37	+15:09:46.2	+67:15:24	-01:02	1.24	2025A-SAO-10	2x3	
tz002208_gf1_1.7170	tz002208_gf1	RV31	600	10:53	+12:50:10.6	-10:59:00	+01:32	1.50	2025A-SAO-24	2x3	Clear; WFS=1.16"
tz002208_gf1_1.7172	tz002208_gf1	RV31	600	11:10	+12:50:10.6	-10:59:00	+01:49	1.56	2025A-SAO-24	2x3	
tz002208_gf1_1.7173	tz002208_gf1	RV31	600	11:21	+12:50:10.6	-10:59:00	+01:59	1.60	2025A-SAO-24	2x3	
domeflat.7174	tz002208_gf1	RV31	8	11:31	+12:50:10.5	-10:59:04	+02:10	1.66	2025A-SAO-24	2x3	
comp.7175	tz002208_gf1	RV31	150	11:32	+12:50:10.5	-10:59:04	+02:11	1.66	2025A-SAO-24	2x3	
tz005170_gf1_1.7176	tz005170_gf1	RV31	600	11:54	+15:12:06.3	+01:00:36	+00:11	1.16	2025A-SAO-24	2x3	Thin clouds; WFS=1.21"
tz005170_gf1_1.7177	tz005170_gf1	RV31	600	12:05	+15:12:06.3	+01:00:36	+00:22	1.16	2025A-SAO-24	2x3	
tz005170_gf1_1.7178	tz005170_gf1	RV31	600	12:15	+15:12:06.3	+01:00:36	+00:32	1.17	2025A-SAO-24	2x3	



UT Date 03/05/2025 Observers KS

File	Title	Filt	Exp	UT	RA	Dec	HA	Air	Prop	Bin	Comments
tz005170_gf1_1.7179	tz005170_gf1	RV31	600	12:26	+15:12:06.3	+01:00:36	+00:43	1.18	2025A-SAO-24	2x3	Extra exp for end-of-night timing
domeflat.7180	tz005170_gf1	RV31	8	12:36	+15:12:06.1	+01:00:32	+00:53	1.19	2025A-SAO-24	2x3	
comp.7181	tz005170_gf1	RV31	150	12:37	+15:12:06.1	+01:00:32	+00:54	1.19	2025A-SAO-24	2x3	
dark.7182	parked	RV31	900	13:03	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
dark.7183	parked	RV31	900	13:18	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
dark.7184	parked	RV31	900	13:34	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
dark.7185	parked	RV31	900	13:49	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
dark.7186	parked	RV31	900	14:05	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
dark.7187	parked	RV31	900	14:20	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
dark.7188	parked	RV31	900	14:36	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
dark.7189	parked	RV31	900	14:51	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
dark.7190	parked	RV31	900	15:07	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x2	
dark.7191	parked	RV31	900	15:22	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	
dark.7192	parked	RV31	900	15:38	-01:00:00.0	-100:00:00	-00:00	1.00	calibratio n	2x3	